

**WATER MANAGEMENT DEPARTMENT**

**Mark S. Hilty,**  
Director



**John C. Schroer**  
Mayor of Franklin

**Eric S. Stuckey**  
City Administrator

---

**HISTORIC  
FRANKLIN  
TENNESSEE**

June 9, 2016

Ms. Ann Rochelle  
Tennessee Department of Environment and Conservation  
711 R.S. Gass Boulevard  
Nashville, TN 37243

RE: Overflow Report – 1003 Market Street  
NPDES Permit# TN0028827

On June 3<sup>rd</sup> 2016 we received a call pertaining to an overflow at the intersection of Market Street and Clovercroft Road at 4:50pm from the HOA office at McKay's Mill subdivision. Crews were dispatched to the location and arrived on site at 6:00pm. After walking the sewer line upstream and downstream from the identified manhole for over an hour with no success in locating the overflow or back up crews notified their Supervisor. We attempted to contact the caller to get a better description of the location, but the number appeared to be a business line and wasn't answered after hours. I left a voicemail with my contact information letting the caller know we could not locate an overflow in the area, but if they could provide a better description of the location crews would be dispatched again. While waiting for the caller to return crews continued to investigate for another hour until the approaching storm created unsafe conditions around 8:00pm.

On June 6<sup>th</sup> 2016 crews returned to the location to follow up on the investigation at 8:30am. At this time, crews did locate the overflowing manhole (same manhole that was checked the previous Friday). The overflow was occurring at a rate of approximately less than one gallon per minute. Crews documented the overflow with photographs and began using the Jet Vac Truck to remove the apparent blockage. Crews noted the overflow ceased at 9:30am. The overflow was caused by a three foot long fence post, 6 inches x 6 inches, lodged into the sewer main. After crews removed the post, CCTV inspection crews were dispatched to the location to inspect the upstream and downstream lines. Inspection crews noted all lines were in proper working condition with appropriate flows. Crews investigated the area and determined the overflow was contained to the ground surface, covering the affected areas with lime. All corrective actions were completed at 11:15am.

I have attached a map of the area.

If you have any question or comments please let me know. I can be reached at (615) 794 – 4554 or at [jrlee@franklintn.gov](mailto:jrlee@franklintn.gov).

Sincerely,

A handwritten signature in black ink, appearing to read 'JR Lee'.

JR Lee  
Assistant Wastewater Collection Superintendent





June 7, 2016



- Plug
- Sewer Service
- Manholes
- Sewer System Valve
- Sewer Force
- Abandoned Collector
- Te
- Existing
- Flow Monitor
- Sewer Lateral Pipe
- Collectors
- Abandoned Interceptor
- Wye
- Proposed
- Rule 1
- Abandoned Force
- Interceptors

THESE DRAWINGS ARE THE PROPERTY OF THE CITY OF FRANKLIN, TENNESSEE. THEY ARE TO BE USED ONLY FOR THE PROJECT AND LOCATION SPECIFICALLY IDENTIFIED HEREON. ANY REUSE OR MODIFICATION OF THESE DRAWINGS WITHOUT THE WRITTEN PERMISSION OF THE CITY OF FRANKLIN, TENNESSEE, IS PROHIBITED. THE CITY OF FRANKLIN, TENNESSEE, ASSUMES NO LIABILITY FOR ANY DAMAGE OR INJURY RESULTING FROM THE USE OF THESE DRAWINGS. THE CITY OF FRANKLIN, TENNESSEE, DOES NOT WARRANT THE ACCURACY OR COMPLETENESS OF THESE DRAWINGS. THE USER OF THESE DRAWINGS SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY PERMITS AND FOR VERIFYING THE ACCURACY OF ALL INFORMATION PROVIDED HEREON. THE CITY OF FRANKLIN, TENNESSEE, SHALL NOT BE RESPONSIBLE FOR ANY CONSEQUENCES ARISING FROM THE USE OF THESE DRAWINGS. THE CITY OF FRANKLIN, TENNESSEE, SHALL NOT BE RESPONSIBLE FOR ANY DAMAGE OR INJURY RESULTING FROM THE USE OF THESE DRAWINGS. THE CITY OF FRANKLIN, TENNESSEE, SHALL NOT BE RESPONSIBLE FOR ANY DAMAGE OR INJURY RESULTING FROM THE USE OF THESE DRAWINGS.



06.06.2016 09:42



JR Lee

---

**From:** JR Lee  
**Sent:** Monday, June 06, 2016 3:05 PM  
**To:** Ann Rochelle (Ann.Rochelle@tn.gov)  
**Cc:** Michelle Hatcher  
**Subject:** Sanitary Sewer Overflow

Ms. Rochelle,

The City of Franklin Water Management Department had an overflow this morning in McKays Mills Subdivision. The overflow was contained to the ground surface. I will send you a report later this week.

Sincerely,

JR Lee  
Assistant Wastewater Collection Superintendent  
City of Franklin Public Works  
Water Management Division  
124 Lumber Dr  
Franklin, TN 37064  
(615) 794-4554  
[Jr.lee@franklintn.gov](mailto:Jr.lee@franklintn.gov)

This message has been prepared on resources owned by the City of Franklin, TN. It is subject to the City's Policy for the Use of Computers, Internet and eMail. Messages that are received or created by any City staff member may be a public record subject to Tennessee Open Records Act, T.C.A. 10-7-503, et seq., and the rules of the Open Records Commission. **DO NOT COPY OR FORWARD TO UNAUTHORIZED PERSONS.** This message may contain confidential information and is intended only for the use of the specific individual(s) to which it is addressed. If you are not an intended recipient of this message, you are hereby notified that any unauthorized use, dissemination or copying of this message or any information it contains is strictly prohibited. If you have received this message in error, please delete it and immediately notify the sender by reply email.



JR Lee

---

**From:** JR Lee  
**Sent:** Thursday, June 09, 2016 7:36 AM  
**To:** Ann Rochelle (Ann.Rochelle@tn.gov)  
**Cc:** Michelle Hatcher  
**Subject:** Sanitary Sewer Overflow  
**Attachments:** SKMBT\_C45216060907380.pdf

Ms. Rochelle,

See attached overflow report for 1003 Market Street. Originals will be sent via postal. If you have any questions or comments you may contact me at the office or email.

Sincerely,

JR Lee  
Assistant Wastewater Collection Superintendent  
City of Franklin Public Works  
Water Management Division  
124 Lumber Dr  
Franklin, TN 37064  
(615) 794-4554  
[Jr.lee@franklintn.gov](mailto:Jr.lee@franklintn.gov)

This message has been prepared on resources owned by the City of Franklin, TN. It is subject to the City's Policy for the Use of Computers, Internet and eMail. Messages that are received or created by any City staff member may be a public record subject to Tennessee Open Records Act, T.C.A. 10-7-503, et seq., and the rules of the Open Records Commission. **DO NOT COPY OR FORWARD TO UNAUTHORIZED PERSONS.** This message may contain confidential information and is intended only for the use of the specific individual(s) to which it is addressed. If you are not an intended recipient of this message, you are hereby notified that any unauthorized use, dissemination or copying of this message or any information it contains is strictly prohibited. If you have received this message in error, please delete it and immediately notify the sender by reply email.



HISTORIC  
FRANKLIN  
TENNESSEE

R. Neena

## Service Request

### REQUEST INFORMATION

Service Request #: 270826

Request Date: 06/06/2016

Priority: 1

Request Type: SSO Public

Assigned To: 2026

Responsible Dept: WATER MANAGEMENT

Source: PHONE

Caller Comments: NO CONTACT GIVEN

Additional Comments or Information: WASTEWATER COMING FROM MANHOLE BESIDE SIDEWALK

### CONTACT INFORMATION

Name: -

Day Phone #:

Cell Phone #:

Email:

Evening Phone #:

Contact Requested: N

### LOCATION INFORMATION

Service Address: 1003 MARKET ST

Subdivision: MCKMIL

COF Water Service Area:

City Limits: INSIDECOF

Location Details:

### RESOURCE USAGE

Employee Name / #	Date	Start Time	End Time	Total Hours
2038-1844	6-3-16	6:00 p	8:00 p	3 hrs 2 hrs
2038-4244-4152	6-6-16	8:30	11:15	2 hrs 45 min
1844				
2016	6-6-16	10:15	11:15	1 hr

Off Truck #	Out of SR	Part Name	Part Number	Quantity Used

Vehicle	Usage
102	5 hrs 45 min
28	2 hrs 45 min
34	1 hr

### Work Comments

Received call of sewer backup on 6-3-16. Arrived on site & searched area. NO backup or overflow found while on site. One main was running slow. Done a return inspection 6-6-16 at 9:00. Found sewer seeping out around lid & casting less than 1 gal. per min.

For additional comments, please use back. start unstop at 9:15. main unstoped & flowing at 9:30. Found a 3ft section of 6x6 post in mtl & main causing problem

~~2016~~

Used upstream & downstream lines. Everything OK.